


Workshop 1: Green Group (Holger, Fiona, Roy S, David, Richard and Katy)



Workshop 1: Green Group (Holger, Fiona, Roy S, David, Richard and Katy)



### Workshop 1: Green Group (Holger, Fiona, Roy S, David, Richard and Katy)




Risk Level at Other Location/s

Where is this risk being transferred to?


Potwell Close

Risk Level at Church St/Easthorpe


Workshop 1: Green Group (Holger, Fiona, Roy S, David, Richard and Katy)




### Workshop 1: Green Group (Holger, Fiona, Roy S, David, Richard and Katy)




Workshop 1: Green Group (Holger, Fiona, Roy S, David, Richard and Katy)




### Workshop 1: Green Group (Holger, Fiona, Roy S, David, Richard and Katy)



Workshop 1: Green Group (Holger, Fiona, Roy S, David, Richard and Katy)





Risk Level at Other Location/s

Where is this risk being transferred to?

Nottingham Road then Church Street

Risk Level at Halloughton Road

Large catchment

Impermeable soil

Water could not get into holding pond from road – poor design

Development issues – low houses

Flooded homes

Damaged road

Could not use road

Risk Level at Other Location/s

Where is this risk being transferred to?

Lowes Wong Sch Traffic risk

Risk Level at Halam Rd/Hopkiln Ln

Catchment

Impassable road

Risk Level at Other Location/s

Culverts under
Nottingham
Road –
engineering
limitations

Flooded properties

Where is this risk being transferred to?

Southwell (transport) Church St (flooding)

Car park (school, leisure centre, homes)

Risk to school pupils

Risk Level at Nottingham Road

3

Surface water

Steep, impermeable catchment

Inadequate drainage system

Poor regulation (e.g. Lowes Wong and Co-op)

Intense rainfall

Flooded properties and roads

Sewers
overwhelmed
and interaction
with foul sewer


Risk Level at Other Location/s

Where is this risk being transferred to?


Crafts Way, Archers Fd, Caudwell Close

Risk Level at Ropewalk

Workshop 1: Yellow Group (Roy L, Jill, Alastair, Peter, Jacky, Rob and Kevin)



Workshop 1: Yellow Group (Roy L, Jill, Alastair, Peter, Jacky, Rob and Kevin)



Inadequate culvert (pinch point) undersize and cramped

Rising ground water

Low lying development

Blockage to downstream

Flooded homes

Main road – traffic stopped

Damaged vehicles

Collapsed walls by watercourse

Risk Level at Other Location/s

Where is this risk being transferred to?

Potwell Close

Risk Level at Church St/Easthorpe

Catchment/ surface water

Risk to residents

Risk Level at Other Location/s

Stream blockages Petrol station and other businesses (pollution)

Where is this risk being transferred to?

.....

Low lying houses

Impassable road

Risk Level at Potwell Close etc...

High density of vulnerable people

Domestic properties